

Modernization Kit No. 4750101 External Bearing Replacement Idler Shaft

Features:

- Easy to maintain
- Easy to change
- Reduce machine downtime when replacing

This feature which is now standard on all new Barry-Wehmiller Bottle Cleaners will greatly reduce maintenance and improve washer performance.

- Extended bearing life results in less frequent bearing maintenance.
- When service is required, the bearing may now be serviced without removing bottle carriers and “breaking” the main chain.
- Increased drive loads that results from wear of the old cast iron bushing are eliminated, which translates into less wear on the drive elements and main chain.

This features should be installed during your next scheduled overhaul or whenever the lower shaft needs repair.

Please contact our Barry-Wehmiller Customer Service Department for details.



Barry-Wehmiller