


## Modernization Kit No. 4750213 “Clean In Place” System



The fresh water rinse section of the Bottle Cleaner is a critical area to keep cleaned and sanitized. For this reason, we have introduced the “Clean In Place” (CIP) System for installation on Barry-Wehmiller Bottle Cleaners. The “Clean In Place” System cleans and sanitizes the crucial rinsing and discharge areas that directly affect the quality of the clean bottle.

During non-production hours cleaning and sanitizing solutions are added to the fresh water tanks for circulation to the recirculated water tank and around the rinsing and discharge areas. This cleaning operation will prevent the accumulation of scale, rust, mold, and bacteria thus ensuring the consistent quality of clean bottles.

This modernization kit is available for installation on existing Model 10, Model 12, Model 14, and System 40 and System 100 Bottle Cleaners.

Please contact our Barry-Wehmiller Service Department for details.

**Barry-Wehmiller**

ACCURACY

Barry-Wehmiller  
Company

Hayssen Sandiacre

Thiele

pneumatic  
SCBLE



Barry-Wehmiller  
International Resources

Marquip WardUnited

DESIGN GROUP



Technologies

Fleetwood Goldco Wyard