

Modernization Kit No. 4750346
Stainless Steel Upper Structure



The upper structure of a pasteurizer, being located in the “vapor zone”, is constantly attacked by all elements of corrosion. If your existing upper structure is mild steel, it demands periodic maintenance such as scaping, wire brushing and painting to extend service life. Due to many corners and small areas of the structure, surface preparation and painting are extremely difficult.

Pasteurizer service life can now be greatly extended by the installation of a stainless steel upper structure. These stainless steel upper structures may be retrofitted in all Barry-Wehmiller pasteurizers.

Please contact your Barry-Wehmiller Customer Service Department for details.